



IECEx Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DE/IBE/QAR11.0003/08	Page 1 of 1
QAR Free Ref. No.:	IB2260056	Status: Issued
Details of change:	Re-assessment	Date of issue: 2022-12-21
Site(s) audited:	FLEXIM Flexible Industriemesstechnik GmbH Boxberger Straße 4 12681 Berlin Germany	Valid until: 2026-03-11 Audit date: 2022-12-07
Issuing ExCB:	IBE - IBExU Institut für Sicherheitstechnik GmbH	
Manufacturer:	FLEXIM Flexible Industriemesstechnik GmbH Boxberger Straße 4 12681 Berlin	
Location of Manufacturer:	Germany	
Product information:	Terminal housing / circuit boards / refractometer / ultrasonic detectors and ultrasonic sensors	
Protection concept:	Flameproof enclosures "d" Powder filling "q" Increased safety "e" Intrinsic safety "i" Type of protection "n" Encapsulation "m" Optical radiation "op" Protection by enclosure "t"	
Related QARs:	<div>DE/IBE/QAR11.0003/00 DE/IBE/QAR11.0003/01 DE/IBE/QAR11.0003/02 DE/IBE/QAR11.0003/03 DE/IBE/QAR11.0003/04 DE/IBE/QAR11.0003/05 DE/IBE/QAR11.0003/06 DE/IBE/QAR11.0003/07</div>	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:	<div>IECEx IBE 08.0006 issue: 1 IECEx IBE 08.0006 issue: 2 IECEx IBE 08.0007X issue: 2 IECEx IBE 08.0007X issue: 3 IECEx IBE 08.0007X issue: 4 IECEx IBE 08.0007X issue: 5 IECEx IBE 08.0007X issue: 6 IECEx IBE 08.0007X issue: 7 IECEx IBE 08.0007X issue: 8 IECEx IBE 08.0007X issue: 9 IECEx IBE 08.0007X issue: 10 IECEx IBE 10.0003X issue: 1 IECEx IBE 10.0003X issue: 2 IECEx IBE 10.0014X issue: 1 IECEx IBE 11.0006X issue: 0 IECEx IBE 11.0006X issue: 1 IECEx IBE 11.0006X issue: 2 IECEx IBE 11.0006X issue: 3 IECEx IBE 11.0006X issue: 4 IECEx IBE 11.0006X issue: 5 IECEx IBE 11.0006X issue: 6 IECEx IBE 11.0008 issue: 0 IECEx IBE 11.0008 issue: 1 IECEx IBE 11.0008 issue: 2 IECEx IBE 11.0008 issue: 3 IECEx IBE 11.0008 issue: 4 IECEx IBE 11.0008 issue: 5 IECEx IBE 11.0008 issue: 6 IECEx IBE 12.0004X issue: 0 IECEx IBE 12.0004X issue: 1 IECEx IBE 12.0005X issue: 0 IECEx IBE 12.0005X issue: 1 IECEx IBE 12.0005X issue: 2 IECEx IBE 12.0005X issue: 3 IECEx IBE 12.0005X issue: 4 IECEx IBE 12.0006 issue: 0 IECEx IBE 12.0006 issue: 1 IECEx IBE 12.0011X issue: 0 IECEx IBE 12.0011X issue: 1 IECEx IBE 12.0020 issue: 0 IECEx IBE 14.0031 issue: 0 IECEx IBE 19.0005X issue: 0 IECEx IBE 20.0015X issue: 0</div>	
Comments:		